



Kay Ivey  
GOVERNOR

**ALABAMA**  
**DEPARTMENT OF TRANSPORTATION**

**AERONAUTICS BUREAU**  
**1409 COLISEUM BOULEVARD**  
**MONTGOMERY, ALABAMA 36110**  
PHONE (334) 242-6820  
FAX (334) 353-6540  
Internet: [www.dot.state.al.us](http://www.dot.state.al.us)



John R. Cooper  
TRANSPORTATION DIRECTOR

October 16, 2024

Ms. Kim Sanderson, P.E.  
County Engineer, Mobile County Commission  
205 Government Street  
Mobile, AL 36644

**Subject: Annual Inspection Report**  
**Jeremiah Denton Airport**

Dear Ms. Sanderson:

An inspection of Jeremiah Denton Airport was conducted by personnel of the Alabama Department of Transportation Aeronautics Bureau on October 9, 2024. The purpose of the inspection was to update the information currently on file regarding the airport and to ascertain compliance with the rules and regulations of the Alabama Department of Transportation governing licensed public-use airports within the State of Alabama.

Attached you will find a copy of the Annual Inspection Report. As noted in the report, the airport meets all requirements for the issuance of an operating license.


If you should have any questions concerning the inspection or corrective actions, please do not hesitate to contact Mr. Caleb Nall with the Aeronautics Bureau at (334) 242-6839.

Sincerely,

Frank Farmer  
Chief, Aeronautics Bureau

Copy: Mr. Will Schuller, FAA/ADO  
Mr. Derrick Owens, FAA/ADO  
Mr. Bobby Odom, Michael Baker Inc.

**October 9, 2024**



# **ANNUAL INSPECTION REPORT**



**JEREMIAH DENTON AIRPORT  
DAUPHIN ISLAND, ALABAMA**

## Alabama Department of Transportation Aeronautics Bureau—Annual Airport Inspection Report

In accordance with the provisions of the Code of Alabama 23-1-357, an inspection of the **Jeremiah Denton Airport** was conducted by **Mr. Caleb Nall** with the Alabama Department of Transportation Aeronautics Bureau on **October 9, 2024**.

The inspection was conducted on the airport under the provisions of the Administrative Code Chapter 450-9-1 for the following areas:

Aeronautics Administrative Code	Inspection Results	Corrective Action	Notes
<b>Approach &amp; Departure Paths</b> Administrative Code 450-9-1-.12 (1)	<i>In Compliance</i>	N/A	N/A
<b>Primary Surface</b> Administrative Code 450-9-1-.12 (2)	<i>In Compliance</i> <i>Maintenance</i>	Remove all brush and trees from within the primary surface.	Brush and trees are growing inside the primary surface.
<b>Runway Safety Area</b> Administrative Code 450-9-1-.12 (3)	<i>In Compliance</i>	N/A	N/A
<b>Airport Markings</b> Administrative Code 450-9-1-.12 (4)	<i>In Compliance</i>	N/A	N/A
<b>Wind Direction Indicator</b> Administrative Code 450-9-1-.12 (5)	<i>In Compliance</i>	N/A	N/A
<b>Airport Lighting</b> Administrative Code 450-9-1-.12 (6)	<i>In Compliance</i>	N/A	N/A
<b>Runway, Taxiway and Apron Conditions</b> Administrative Code 450-9-1-.12 (7)	<i>In Compliance</i>	N/A	N/A
<b>Fueling Area Requirements</b> Administrative Code 450-9-1-.12 (8)	<i>In Compliance</i>	N/A	No fuel at this location.
<b>Prohibited Activities</b> Administrative Code 450-9-1-.16	<i>In Compliance</i>	N/A	No evidence of prohibited activities were found.
<b>Additional Items</b> Administrative Code 450-9-1-.16	N/A	N/A	N/A

### License Status—**COMPLIANCE**

The corrective actions that may be prescribed in this inspection report do not relieve the airport sponsor from compliance with any other Federal, State or local laws, ordinances or regulations that may be applicable. It is the responsibility of the airport sponsor to be aware of and obey all Federal, State or local laws, ordinances or regulations that may have a bearing on the corrective actions that may be specified in this report.

**Code of Alabama 23-1-357(a)**... a person or municipality may not operate an airport, restricted landing area, or other navigation facility without a license issued by this Department.

## H.L. “Sonny” Callahan Airport

### Approach and Departure Paths—RUNWAY 12

Administrative Code 450-9-1-.12(1)



No Obstructions were located in the ALDOT Approach/  
Departure Path of Runway 12.

## H.L. “Sonny” Callahan Airport

### Approach and Departure Paths—RUNWAY 30

Administrative Code 450-9-1-.12(1)



No Obstructions were located in the ALDOT Approach/  
Departure Path of Runway 30.

## H.L. “Sonny” Callahan Airport

### Primary Surface

Administrative Code 450-9-1-.12(2)



Primary Surface **DOES NOT MEET** state licensing standards.  
**Maintenance:** Please remove all brush and trees within the primary surface.

## H.L. “Sonny” Callahan Airport

### Runway Safety Area

Administrative Code 450-9-1-.12(3)



Runway Safety Area **MEETS** state licensing standards.

## H.L. “Sonny” Callahan Airport

### Airport Markings—Runway

Administrative Code 450-9-1-.12(4)



Runway markings are in **GOOD** condition.

## H.L. “Sonny” Callahan Airport

### Airport Markings—Taxiway

Administrative Code 450-9-1-.12(4)



Taxiway markings are in **GOOD** condition.

## H.L. “Sonny” Callahan Airport

### Airport Markings—Apron

Administrative Code 450-9-1-.12(4)



Apron markings are in **FAIR** condition.

## H.L. “Sonny” Callahan Airport

### Wind Direction Indicator

Administrative Code 450-9-1-.12(5)



Wind direction indicator is in **GOOD** condition.

## H.L. “Sonny” Callahan Airport

### Airport Lighting

Administrative Code 450-9-1-.12(6)

An inspection of the lighting system had the following results:

<b>Runway Lights</b>	0 inoperable
<b>Taxiway Lights</b>	0 inoperable
<b>Threshold Lights</b>	0 inoperable
<b>PAPI</b>	N/A
<b>REIL</b>	N/A

**MEETS** State Licensing Standards for night-time operation.

## H.L. “Sonny” Callahan Airport

### Runway, Taxiway and Apron Conditions—RUNWAY

Administrative Code 450-9-1-.12(7)



Runway surface is in **FAIR** condition.

## H.L. “Sonny” Callahan Airport

### Runway, Taxiway and Apron Conditions—TAXIWAY

Administrative Code 450-9-1-.12(7)



Taxiway surface is in **GOOD** condition.

## H.L. “Sonny” Callahan Airport

### Runway, Taxiway and Apron Conditions—APRON

Administrative Code 450-9-1-.12(7)



Apron surface is in **GOOD** condition.

## H.L. “Sonny” Callahan Airport

### Fueling Area Requirements

Administrative Code 450-9-1-.12(8)



No fuel at this location.

## H.L. “Sonny” Callahan Airport

### Prohibited Activities


Administrative Code 450-9-1-.16



No prohibited activities were observed during this inspection. All gates were locked and airfield was secured.

# APPENDIX 1

Approach and Departure Path Dimensions			
Inner Width	Outer Width	Length	Acreage
250 Feet	450 Feet	1,000 Feet	8.04 Acres
Primary Surface Dimensions			
250 Feet Wide Centered Along Runway Centerline			
Extending 200 Feet Past the Runway End			
Runway Safety Area Dimensions			
120 Feet Wide Centered Along Runway Centerline			
Extending 200 Feet Past the Runway End			



# Appendix 2

Jeremiah Denton Airport  
Dauphin Island, AL  
Runway 12  
Obstruction Evaluation  
October 9, 2024



# Appendix 3

Jeremiah Denton Airport  
Dauphin Island, AL  
Runway 30  
Obstruction Evaluation  
October 9, 2024



ALDOT 20:1 APP/DEP PATH

FAA 20:1 PART 77 SURFACE

